Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L44	1	(ESD near2 damping and ESD near3 triggering and ESD near2 disabling).clm.	US-PGPUB	OR	ON	2006/10/01 18:53

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	(("5255146") or ("5978192")).PN.	US-PGPUB; USPAT	OR	OFF	2006/10/01 17:42
L2	4	("4363068" "4692834" "4787007" "4890187").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 17:45
L3	611	(latch latching) near2 (circuit device) and ESD .	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 17:49
L4	29381	(RC near2 delay RC near2 timer RC near2 detection RC near2 circuit)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 17:49
L5	57	3 and 4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 17:49
L6	5	("20030007301" "20030214773" "20040195629" "5289334" "5504451").PN.	US-PGPUB; USPAT; USOCR	OR	ON .	2006/10/01 17:51
L7	4	("5255146" "5400202" "5463520" "5528188").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 17:53
L8	. 19	("4107556" "4254347" "4558233" "4633107" "4888497" "4922133" "4970408" "5051611" "5111067" "5136181" "5159206" "5180926" "5200648" "5237395" "5239440" "5255146" "5311391" "5323067" "5349559").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 17:54
L9	1	("4870530").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 17:55
L10	30	("5239440").URPN.	USPAT	OR	ON	2006/10/01 17:55
L11	11	("20020153533" "3612915" "4396999" "4496854" "5239440" "5276350" "5276582" "5538907" "6465848" "6560081" "6670792").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 17:55
L12	11	("20030147190" "20030214773" "4829350" "5239440" "5301084" "5400202" "5521789" "6204715" "6285536" "6400540" "6552886").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 17:59
L13	5	("5239440" "5838146" "6104588" "6400540" "6538868").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 18:02
L14	4	("5239440" "5671111" "5721656" "5986867").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 18:03
L15	11	("3636385" "5023542" "5239440" "5345357" "5400202" "5418411" "5452171" "5526214" "5745323" "5825601" "5838146").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 18:05

L16	26367	(disable disabling) near2 (circuit device)	US-PGPUB;	OR	ON	2006/10/01 18:07
	20307	(Since and any man a for our device)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB			
L17	107	4 same 16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:07
L18	2187	4 same (reset override)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:13
L19	87776	(overvoltage electrostatic near4 surge electrostatic near3 discharge ESD voltage near2 surge voltage near2 transient)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:10
L20	281	18 and 19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:48
L21	845	4 with (reset override)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/10/01 18:13
L22	166	19 and 21	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:14
L23	11	19 same 21	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:16
L24	8005	(failse failure false) near3 (triggering trigger)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:15
L25	11	4 with 24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:49

			•			
L26	49	4 same 24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:16
L27	2293	(361/56).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/10/01 18:16
L28	0	("04and27").PN.	US-PGPUB; USPAT	OR	OFF	2006/10/01 18:16
L29	187	4 and 27	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:23
L30	623	(361/91.1).CCLS.	US-PGPUB; USPAT	OR	OFF ·	2006/10/01 18:23
L31	35	4 and 30	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:25
L32	1602	(361/111).CCLS.	US-PGPUB; USPAT	OR .	OFF	2006/10/01 18:25
L33	113	4 and 32	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:46
L34	3360	(361/56-58).CCLS.	US-PGPUB; USPAT	OR	OFF	2006/10/01 18:45
L35	212	4 and 34	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	. 2006/10/01 18:46
L36	. 38	35 and feedback	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:46
L37	4	("5255146" "5400202" "5463520" "5528188").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/01 18:46
L38	56	34 and 24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:48
L39	146	sigmatel.as.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:48

L40	4	39 and 19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:48
L41	3	39 and 24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:49
L42	51136	takeda.in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:49
L43	4	24 and 42	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/10/01 18:53
L44	.1	(ESD near2 clamping and ESD near3 triggering and ESD near2 disabling).clm.	US-PGPUB	OR	ON	2006/10/01 18:53